

# ALL PURPOSE PROTECTIVE COAT



## A Premixed Slurry Designed to Improve Accuracy

All Purpose Protective Coat is a slurry consisting of refractory powders and a specialized liquid binder specifically designed to be used as a wash coat for refractory models made in Perflex® duplicating material and as a face coat for plastic/wax patterns.

The use of All Purpose Protective Coat during the refractory model and investing steps, will help ensure optimal surface smoothness, thereby improving accuracy and minimizing finishing time and labor.

## Typical Material Properties\*

Specific Gravity	pH
1.76-1.82	11.30-11.85

\*These results are based on the testing methods, frequency and procedures of Ransom & Randolph or its approved suppliers. The levels referenced herein are only for general guidance and do not constitute a firm specification.

## Application Instructions for Refractory Models Made in Perflex Duplicating Material

1. Soak the master model for 15-20 minutes in 90-100° F (32-38° C) water before pouring Perflex duplicating material.
2. Remove the master model and gently air dry the mold to remove any excess condensate.
3. Pour the All Purpose Protective Coat into the Perflex mold, uniformly coating the entire mold cavity.
4. Invert the mold and shake or vibrate to remove all excess All Purpose Protective Coat.
5. Allow the mold to bench set for several minutes. As soon as the All Purpose Protective Coat surface loses its gloss, immediately pour the investment mix into the Perflex mold with vibration.

**Note:** Do not allow the All Purpose Protective Coat to dry completely before pouring the investment mix into the mold. If a large number of molds are to be poured, the working time of the molds containing All Purpose Protective Coat can be increased by storing the molds in a refrigerator at 52° F (11° C).

## Application Instructions Following Partial Denture Wax-Up

1. Apply the All Purpose Protective Coat with a soft brush to all areas of the patterns, wax and sprues. If brushed properly the coating will adhere evenly to all the wax and pattern surfaces.
2. If necessary, repeat the brush application of the All Purpose Protective Coat until all the pattern and wax areas remain coated.
3. Vigorously shake the refractory model to remove all the excess All Purpose Protective Coat.
4. Allow the coat to dry for approximately 10-15 minutes before pouring the backup investment mix.

## Application Instructions for Crown & Bridge Wax-Up

1. Securely attach the sprued wax-up on a base using wax.
2. Carefully apply All Purpose Protective Coat using a soft brush to all the surfaces of the wax-up, including the sprues, until all areas remain coated.
3. Vigorously shake to remove all the excess All Purpose Protective Coat.
4. Allow the All Purpose Protective Coat to dry for a minimum of 15 minutes before proceeding with the investing procedure.

## Precautions

- Use with adequate ventilation.
- Stir material then shake container thoroughly before use.



## RANSOM & RANDOLPH

3535 Briarfield Boulevard | Maumee, OH 43537 USA  
800.800.7496 | 419.865.9497 | 419.865.9997 (FAX)  
www.ransom-randolph.com



Made in the USA

Ransom & Randolph GmbH  
Leipziger Straße 40 | 04571 Rötha Germany  
+49 342 06373999

Investing with Innovation™

---

# ALL PURPOSE PROTECTIVE COAT

---

## Storage

Keep container tightly closed when not in use to avoid evaporation and excessive thickening of the material. Store locked up. Store in a cool, dry area between 60-80°F (16-27°C).

## Safety

Danger. Contains crystalline silica quartz. May cause cancer if inhaled. Causes damage to organs through prolonged or repeated exposure by inhalation. Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Do not breathe mist. Wash thoroughly after handling. Do not eat, drink, or smoke when using this product. Wear protective gloves/protective clothing/eye protection/face protection. If feeling unwell, get medical advice/attention. See SDS for more information.

*As the conditions or methods of use are beyond our control, we do not assume any responsibility and expressly disclaim any liability for any use of this product. Information contained herein is believed to be true and accurate but all statements or suggestions are made without warranty, expressed or implied, regarding accuracy of the information, the hazards connected with the use of the material or the results to be obtained from the use thereof. Compliance with all applicable federal, state, and local regulations remains the responsibility of the user. All potential liability related to the sale and use of this product is limited to the cost of the particular goods sold in their respective transactions.*



---

## RANSOM & RANDOLPH

3535 Briarfield Boulevard | Maumee, OH 43537 USA  
800.800.7496 | 419.865.9497 | 419.865.9997 (FAX)  
[www.ransom-randolph.com](http://www.ransom-randolph.com)



Made in the USA

Issue Date: February 15, 2024

Ransom & Randolph GmbH  
Leipziger Straße 40 | 04571 Rötha Germany  
+49 342 06373999

*Investing with Innovation™*